


# *Serial cable for Cutline*

*(Macintosh ↔ Cutting Machine)*

**Macintosh Side**  
MINI DIN 8 (Male)

**Cutter Side**  
DB-25 (Male)



Connect cable shield and ground wire to the shield of the MINI DIN 8 connector and pin 1 of the DB-25 connector.